

W1

W1 = Overall Height - PC - BC size

Plum Cut

TC Size (run)

Pitch (Pitch)

Solve for (Diag)

Overall Height

1/2 Span (run)

Pitch (pitch)

Solve for (Rise)

Rise + Haps

HAP (Height At Plate)

HAP = PC + ButtCut

Shipping Hgt.

1/2 Span + OH (Run)

Pitch (Pitch)

Solve for (Rise)

Rise + PC

Top Cord Length

1/2 Span + OH (Run)

Pitch (Pitch)

Solve for (Diag)

C

By **slamjak**
cheatography.com/slamjak/

Not published yet.
Last updated 23rd October, 2017.
Page 1 of 1.

Sponsored by **Readability-Score.com**
Measure your website readability!
<https://readability-score.com>